



NUEVOS LANZAMIENTOS

23817816CFP

BALATA DISCO DEL
GM AVEO III 23-25 1.5L
CERAMICA
FP



9506-D2266CFP

BALATA DISCO DEL
GM GROOVE 22-25 1.5L
23623634
CERAMICA
FP



23623675CFP

BALATA DISCO DEL
GM CAPTIVA 23-25 1.5T
CERAMICA
FP



8806-D2190CFP

BALATA DISCO DEL
KIA RIO II 18-23 1.6L
CERAMICA
FP



9523-D2287CFP

BALATA DISCO DEL
KIA SOUL 20-24 1.6L 2.0L
CERAMICA
FP



9626-D2398CFP

BALATA DISCO DEL
KIA SPORTAGE 23-24 2.5L 1.6T
HY TUCSON 21-24 2.0L 2.4L 2.5L 1.6T
CERAMICA
FP



Av. Javier Rojo Gómez No. 1350 Col. San Miguel, C.P. 09360, CDMX

55 5716 1400

Nikko Autoparts

NIKKO
— AUTO-PARTS

No. 54
Enero 2025
Pág. 1 de 2



NUEVOS LANZAMIENTOS

8423-D1308CFP

BALATA DISCO DEL
MINI COOPER 07-21 1.6T
DIAM 294MM
CERAMICA
FP



9609-D2381CFP

BALATA DISCO TRAS
HY SANTA FE 22-23 2.5L 1.6H
CERAMICA
FP



9486-D2250CFP

BALATA DISCO DEL
GM SILVERADO 2500HD 20-22 6.6L
SILVERADO 3500HD 20-22 6.6L
S/SENSOR
CERAMICA
FP



9540-D2305CFP

BALATA DISCO TRAS
TY HIGHLANDER 20-23 2.5L 3.5L
CERAMICA
FP



Av. Javier Rojo Gómez No. 1350 Col. San Miguel, C.P. 09360, CDMX

55 5716 1400

Nikko Autoparts

NIKKO
— AUTO-PARTS

No. 54
Enero 2025
Pág. 2 de 2