

10502236VM

SENSOR ARBOL LEVAS
MG MG5 21-24 1.5L
ZS 21-24 1.5L
HS 21-25 1.5T 2.0T
CR JOURNEY 22-24 1.5T
VOLTMAX



22495VM

SENSOR ARBOL LEVAS
GM SPARK II 16-21 1.4L
CRUZE 16-18 1.4T
EQUINOX 18-23 1.5T
PC1138
VOLTMAX



22491VM

SENSOR ARBOL LEVAS
GM MALIBU 13-18 2.0T 2.5L
COLORADO 16-19 2.0T 2.5L
C/TORNILLO
PC1006
VOLTMAX



22259VM

SENSOR ARBOL LEVAS
GM AVEO II 18-23 1.5L
CAVALIER 18-21 1.5L
C/TORNILLO
PC655
VOLTMAX



39350-2M327VM

SENSOR ARBOL LEVAS
HY CRETA 21-24 1.5L
KIA SELTOS 24-25 1.5L
VOLTMAX



22342VM

SENSOR ARBOL LEVAS
FD ECOSPORT 10-12 2.0L
MAZDA 3 06-13 2.0L
ESCAPE 09-19 2.5L
RANGER 13-22 2.5L
PC761
VOLTMAX



nikkoauto.mx

Av. Javier Rojo Gómez No. 1350 Col. San Miguel, C.P. 09360, CDMX

55 5716 1400

Nikko Autoparts

NIKKO
— AUTO-PARTS

No. 218
Junio 2025
Pág. 1 de 2

22365VM

SENSOR ARBOL LEVAS
CR JOURNEY 11-19 3.6L
GRAND CHEROKEE 11-23 3.6L
CHARGER 11-18 3.6L
RAM 1500 14-19 3.6L
C/TORNILLO
PC950
VOLTMAX



22811VM

SENSOR ARBOL LEVAS
GM COLORADO 17-22 3.6L
BLAZER 19-22 3.6L
ACADIA 17-21 3.6L
PC1113
VOLTMAX



22806VM

SENSOR ARBOL LEVAS
GM EQUINOX 07-08 3.4L
UPLANDER 07-08 3.9L
MONTANA 07-08 3.9L
PC653
VOLTMAX



22497VM

SENSOR ARBOL LEVAS
KIA SPORTAGE 17-22 2.0L 2.4L
SORENTO 16-20 2.4L
HY TUCSON 19-21 2.4L
PC1045
VOLTMAX



22343VM

SENSOR ARBOL LEVAS
FD TRANSIT 07-13 2.2TDI
TRANSIT 16-20 3.7L
VOLTMAX

