

04E-905-110PVM

BOBINA
VW JETTA A7 19-25 1.4T
TIGUAN 18-24 1.4T
VIRTUS 20-25 1.6L 1.0T
ST IBIZA 18-25 1.6L 1.0T
IC-368
VOLTMAX



IC607VM

BOBINA
CR PROMASTER RAPID 17-24 1.4L
FT UNO 13-20 1.4L
UF920
VOLTMAX



IC905VM

BOBINA
RN DUSTER 21-25 1.6L
KANGOO 19-25 1.6L
STEPWAY 20-24 1.6L
LOGAN 23-24 1.6L
VOLTMAX



IC1311VM

BOBINA
JAC FRISON T6 T8 19-25 2.0T
VOLTMAX



IC793VM

BOBINA
MINI COOPER 09-13 1.6T
BMW 120 05-12 2.0L
130i 06-10 3.0L
325i 03-13 2.5L
VOLTMAX



IC1400VM

BOBINA
VO XC90 03-06 2.5T 2.9T
C70 00-04 2.3T
S60 01-05 2.0T 2.3T 2.5T
S80 99-06 2.9L 2.5T
UF341
VOLTMAX



nikkoauto.mx

Av. Javier Rojo Gómez No. 1350 Col. San Miguel, C.P. 09360, CDMX

55 5716 1400

Nikko Autoparts

NIKKO
— AUTO-PARTS

No. 36
Febrero 2026
Pág. 1 de 2

IC1651VM

BOBINA
KIA SPORTAGE 95-02 2.0L
VOLTMAX



IC1130VM

BOBINA
NS PATHFINDER 00-01 3.3L 3.5L
UF-331
VOLTMAX




IC1500VM

BOBINA
JG S-TYPE 03-08 2.5L 3.0L
X-TYPE 01-08 2.5L 3.0L
UF435
VOLTMAX



IC405VM

BOBINA
FD FIESTA 03-10 1.6L
IKON 01-07 1.6L
KA 01-08 1.6L
COURIER 01-12 1.6L
RANGER 01-12 2.3L
DISEÑO BOSCH
VOLTMAX



nikkoauto.mx

Av. Javier Rojo Gómez No. 1350 Col. San Miguel, C.P. 09360, CDMX

55 5716 1400

Nikko Autoparts

NIKKO
— AUTO-PARTS

No. 36
Febrero 2026
Pág. 2 de 2